



---

# *ABS RING DESIGNS & APPLICATIONS*












---

MANUFACTURER OF CONSTANT VELOCITY DRIVEAXLE COMPONENTS  
1500 11TH AVENUE ROCKFORD, ILLINOIS 61104  
PHONE (815) 962-1411 FAX (815) 962-4857

**GENUINE  
ROCKFORD  
CONSTANT VELOCITY**

**166-19  
to  
214-19A**













**ABS Ring**

<p><b>166-19</b> -<u>ABS RING</u> 1989-1994 Nissan Maxima 1990-1992 Nissan Stanza</p>  <p>46 Teeth</p>	<p><b>188-19</b> -<u>ABS RING</u> 1990-1997 Acura Integra 1993-1996 Honda Civic Del Sol</p>  <p>50 Teeth</p>
<p><b>175-19</b> -<u>ABS RING</u> 1988-1991 Mazda 929</p>  <p>90 Teeth</p>	<p><b>189-19</b> -<u>ABS RING</u> 1997-1998 Acura 3.0CL 1989-1990 Acura Legend 1995-1997 Acura TL 1990-1997 Honda Accord 1990-1991 Honda Prelude</p>  <p>50 Teeth</p>
<p><b>176-19</b> -<u>ABS RING</u> 1988-1993 Toyota Celica</p>  <p>48 Teeth</p>	<p><b>189-19A</b> -<u>ABS RING</u> 1992-1994 Acura Vigor 1992-1996 Honda Prelude</p>  <p>50 Teeth</p>
<p><b>178-19</b> -<u>ABS RING</u> 1992-1996 Lexus ES300 1995-1996 Toyota Avalon 1992-1996 Toyota Camry</p>  <p>48 Teeth</p>	<p><b>191-19</b> -<u>ABS RING</u> 1991-1995 Acura Legend 1991-1997 Acura NSX</p>  <p>50 Teeth</p>
<p><b>178-19A</b> -<u>ABS RING</u> 1993-1998 Mercury Villager 1993-1998 Nissan Quest</p>  <p>50 Teeth</p>	<p><b>214-19</b> -<u>ABS RING</u> 1995-1997 Dodge Neon 1995-1997 Plymouth Neon</p>  <p>56 Teeth</p>
<p><b>183-19</b> -<u>ABS RING</u> 1995-1997 Hyundai Accent</p> <p><i>Illustration not available at this time</i></p> <p>25 Teeth</p>	<p><b>214-19A</b> -<u>ABS RING</u> 1995-1998 Ford Contour 1995-1998 Mercury Mystique</p>  <p>44 Teeth</p>

**GENUINE  
ROCKFORD  
CONSTANT VELOCITY**

**215-19  
to  
441-19**

**ABS Ring**

<p><b>215-19 -ABS RING</b> 1992-1995 Chrysler Town &amp; Country 1991-1995 Dodge Caravan 1991-1995 Plymouth Voyager</p>  <p>47 Teeth</p>	<p><b>335-19A -ABS RING</b> 1990-1993 Saab 9000</p>  <p>46 Teeth</p>
<p><b>216-19 -ABS RING</b> 1989-1995 Chrysler A Body* 1988-1990 Chrysler C Body* 1987-1987 Chrysler E Body* 1987-1990 Chrysler G, H, P Body* 1987-1989 Chrysler K Body* 1996-1998 Chrysler NS Body* 1987-1995 Chrysler S Body* 1989-1991 Chrysler TC By Maserati</p>  <p>47 Teeth</p>	<p><b>335-19B -ABS RING</b> 1986-1988 Audi 5000</p>  <p>96 Teeth</p>
<p><b>216-19A -ABS RING</b> 1986-1990 British Sterling 825SL</p>  <p>45 Teeth</p>	<p><b>335-19C -ABS RING</b> 1989-1991 Audi 100</p>  <p>45 Teeth</p>
<p><b>275-19 -ABS RING</b> 1992-1992 Dodge Monaco 1992-1992 Eagle Premier</p>  <p>47 Teeth</p>	<p><b>440-19 -ABS RING</b> 1986-1991 General Motors C Body* 1988-1992 General Motors E Body* 1986-1991 General Motors H Body* 1986-1991 General Motors K Body* 1989-1992 General Motors V Body*</p>  <p>47 Teeth</p>
<p><b>320-19 -ABS RING</b> 1984-1992 BMW 318i 1987-1991 BMW 320i 1987-1991 BMW 320is 1984-1988 BMW 325e 1987-1993 BMW 325i 1987-1991 BMW M3</p>  <p>48 Teeth</p>	<p><b>440-19A -ABS RING</b> 1987-1988 Buick Century 1987-1988 Pontiac 6000</p>  <p>98 Teeth</p>
<p><b>335-19 -ABS RING</b> 1985-1989 Saab 9000</p>  <p>94 Teeth</p>	<p><b>441-19 -ABS RING</b> 1991-1993 Chrysler Imperial 1991-1995 Chrysler Lebaron 1991-1993 Chrysler New Yorker 1991-1993 Dodge Daytona 1991-1993 Dodge Dynasty 1991-1994 Dodge Shadow 1991-1994 Plymouth Sundance</p>  <p>47 Teeth</p>

\*Chrysler & General Motors body types & axle design information is located in the Reference

**GENUINE  
ROCKFORD  
CONSTANT VELOCITY**

**441-19A  
to  
714-19A**

**ABS Ring**

**441-19A -ABS RING**

1993-1997 Chrysler Concorde  
1994-1997 Chrysler LHS  
1993-1997 Dodge Intrepid  
1993-1997 Eagle Vision



50 Slots

**627-19 -ABS RING**

1988-1992 Ford Probe  
1988-1992 Mazda 626  
1988-1992 Mazda MX6  
1991-1992 Mitsubishi 3000 GT



90 Teeth

**550-19 -ABS RING**

1993-1997 Lexus GS300  
1990-1991 Lexus LS400  
1992-1997 Lexus SC300  
1992-1997 Lexus SC400



48 Teeth

**627-19A -ABS RING**

1991-1992 Dodge Stealth  
1991-1992 Mitsubishi 3000 GT



47 Teeth

**625-19 -ABS RING**

1994-1996 Ford Escort  
1992-1994 Mazda MX3  
1992-1994 Mazda Protege  
1994-1996 Mercury Tracer



44 Teeth

**627-19B -ABS RING**

1993-1995 Nissan Altima



44 Teeth

**626-19 -ABS RING**

1991-1993 Infinity G20



42 Teeth

**627-19C -ABS RING**

1992-1994 Hyundai Sonata  
1994-1997 Mazda Millenia



47 Teeth

**626-19A -ABS RING**

1991-1993 Nissan NX  
1991-1994 Nissan Sentra



42 Teeth

**714-19 -ABS RING**

1988-1997 Ford Taurus  
1988-1992 Lincoln Continental  
1988-1995 Mercury Sable



50 Teeth

**626-19B -ABS RING**

1996-1997 Mitsubishi Eclipse  
1994-1997 Mitsubishi Galant



43 Teeth

**714-19A -ABS RING**

1993-1997 Ford Probe  
1993-1997 Mazda 626  
1994-1997 Mazda Millenia  
1993-1997 Mazda MX6















44 Teeth

**GENUINE  
ROCKFORD  
CONSTANT VELOCITY**

**714-19B  
to  
915-19**

**ABS Ring**

<p><b>714-19B -ABS RING</b> 1995-1998 Ford Windstar</p>  <p>50 Teeth</p>	<p><b>719-19 -ABS RING</b> 1993-1997 Jeep Grand Cherokee 1993-1993 Jeep Grand Wagoneer</p>  <p>54 Teeth</p>
<p><b>714-19C -ABS RING</b> 1988-1992 Jeep Cherokee</p>  <p>54 Teeth</p>	<p><b>804-19 -ABS RING</b> 1992-1995 BMW 325i 1996-1997 BMW 328i</p>  <p>48 Slots</p>
<p><b>714-19D -ABS RING</b> 1995-1997 Ford Taurus</p>  <p>50 Teeth</p>	<p><b>815-19 -ABS RING</b> 1988-1994 Buick Regal 1992-1994 Chevrolet Lumina 1988-1994 Oldsmobile Cutlass Supreme 1988-1994 Pontiac Grand Prix</p>  <p>47 Teeth</p>
<p><b>714-19E -ABS RING</b> 1995-1998 Ford Contour 1995-1998 Mercury Mystique</p>  <p>44 Slots</p>	<p><b>816-19 -ABS RING</b> 1992-1998 Chevrolet K1500 4X4 1990-1998 Chevrolet K2500 4X4 1990-1998 Chevrolet K3500 4X4</p>  <p>55 Teeth</p>
<p><b>715-19 -CONVERSION ABS RING</b> 1986-1995 Ford Taurus 1986-1995 Mercury Sable (Converts 715 Series Shaft w/o ABS to fit Applications w/ABS)</p>  <p>50 Teeth</p>	<p><b>914-19 -ABS RING</b> 1991-1995 Saturn Coupe</p>  <p>47 Teeth</p>
<p><b>716-19 -ABS RING</b> 1989-1997 Ford Thunderbird 1989-1997 Mercury Cougar</p>  <p>50 Teeth</p>	<p><b>915-19 -ABS RING</b> 1991-1995 Buick Skylark 1988-1995 Chevrolet Beretta 1992-1994 Chevrolet Cavalier 1992-1995 Chevrolet Corsica 1992-1995 Oldsmobile Achieva 1991-1991 Oldsmobile Calais 1991-1995 Pontiac Grand Am 1992-1994 Pontiac Sunbird</p>  <p>48 Teeth</p>

# **ABS RINGS**

## **Sorted by Number of Teeth**

<b>Part #</b>	<b>Teeth</b>	<b>Outside Dia.</b>	<b>Inside Dia.</b>	<b>Part #</b>	<b>Teeth</b>	<b>Outside Dia.</b>	<b>Inside Dia.</b>
183-19	25	3.582	2.983	189-19	50	3.863	3.498
182-19	42	3.031	2.483	189-19A	50	3.863	3.581
626-19A	42	3.068	2.677	714-19B	50	3.984	3.414
626-19B	43	3.070	2.595	714-19D	50	4.100	3.325
627-19B	44	3.425	3.030	715-19	50	4.105	3.345
714-19E	44 Slots	3.550	3.422	714-19	50	4.106	3.403
625-19	44	3.552	2.952	716-19	50	4.416	2.556
214-19A	44	3.582	3.231	191-19	50	4.435	3.991
714-19A	44	3.807	3.069	714-19C	54	3.54	2.736
335-19C	45	2.895	2.523	719-19	54	3.583	2.736
216-19A	45	4.055	3.482	816-19	55	4.759	3.922
335-19A	46	3.111	2.205	214-19	56	3.672	3.154
166-19	46	3.782	3.381	175-19	90	3.621	3.071
914-19	47	3.296	2.904	626-19	90	3.805	3.066
627-19A	47	3.348	2.357	627-19	90	3.805	3.066
275-19	47	3.552	3.105	335-19	94	3.111	2.205
441-19	47	3.761	3.025	335-19B	96	2.895	2.522
215-19	47	3.761	3.306	440-19A	98	3.503	3.240
216-19	47	3.761	3.306	441-19A	50 Slots	3.540	3.398
440-19	47	3.779	3.392				
627-19C	47	4.005	3.560				
815-19	47	4.192	3.397				
335-19D	48	3.203	2.836				
320-19	48	3.442	2.896				
178-19	48	3.507	3.147				
176-19	48	3.683	3.145				
915-19	48	3.723	3.183				
550-19	48	3.783	3.150				
188-19	50	3.587	3.294				
178-19A	50	3.788	3.384				

PLEASE NOTIFY TECHNICAL DEPT. OF NEW APPLICATIONS AND PLEASE  
 TRY TO SUPPLY THE CRITICAL INFORMATION SHOWN ABOVE.  
 PHONE (815)-962-1411 - FAX (815)-962-4857